Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/90009MD1054/1
Work Order Type: Weatherization

Audit Name: Audit (34)

CL	IEN	١T	INI	FOI	RMA	TION

Client Name: Address:

Client ID: 90009MD1054

Alt. Client ID:

AGENCY INFORMATION

Agency: Metropolitan Development Housing Agency Agency Phone:

Address: 701 South 6th Street Fax:

Nashville, TN 37206 *Email Address:*

Company Name & License Number:	
Contractor's Signature	

<u>COMMENT</u>

Measures

I	Measure 1		all R-30 fiberglass batts ess and ws with foam t			Componen	ts			Inspected
С	omment					Estimated	,		Actual	
#	Material / Lab	or	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified		Misc Material	Each	1					
C	Other Detail							1		
					Measur	e Sub Total:			Sub Total:	
	Measure 2 omment	Furn	nace Tuneup			Componen			Actual	Inspected
#	Material / Lab	or	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1			Furnace Tuneup	Each	1					
2	Labor		Furnace Tuneup	Each	1					
C	Other Detail									
					Measur	e Sub Total:			Sub Total:	
	Field Notes:									

Measure 3 A/	C Tuneup			Componen	ts AC1			Inspected
Comment								
# ##	5 10	11-24-		Estimated			Actual	T-4-1
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Cooling Equipm	en A/C Tuneup	Each	1					
2 Labor	A/C Tuneup	Each	1					
Other Detail				1				
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
Measure 4 W	indow Sealing			Component			-, ,	Inspected
						3,WD19		
							VD9,WD	
							D14,WD	
						1,WD3 1,WD12		
Commont					VVD	1, 000 12	-, VV D¬	
Comment				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Windows	Window Sealing	Each	19					
		Window						
2 Labor	Window Sealing	Each	19					
		Window						
Other Detail				,		,		
		ı	Measur	e Sub Total:			Sub Total:	
Field Notes:								

	Measure 5 DWF	H Pipe Insulation			Componen	ts			Inspected
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
2	Labor	DHW Pipe Insulation	Each	1					
(Other Detail						1		
L]		
				Measur	e Sub Total:			Sub Total:	
	Measure 6 DWH	H Tank Insulation			Componen	ts			Inspected
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equip	DHW Tank Insulation	Each	1					
2	Labor	DHW Tank Insulation	Each	1					
(Other Detail								
				Measur	e Sub Total:] ;	Sub Total:	
	Field Notes:								

Measure 7 Ligh	nting Retrofits			Componen	ts LT1			Inspected
Comment				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Lighting	Compact FI 13 Watt	Each Lamp	16					
2 Labor	Compact FI 13 Watt	Each Lamp	16					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Measure 8 Wal	Il Insulation			Componen		WL2,W	,	Inspected
# Material / Labor	Description / Comment	Units	Qty	Estimated Unit Cost	Total	Qty	Actual Unit Cost	Total
1 Insulation	Wall Insulation - Cellulose, Blown - 2x4 Filled	SqFt	1035	Omi Cost	Total	Qiy	Omit Cost	rotar
2 Labor	Wall Insulation - Cellulose, Blown - 2x4 Filled	SqFt	1035					
Other Detail][1		
			Measur	e Sub Total:			Sub Total:	
Field Notes:							•	

Page 5 of 10

Measure 9 Floo Comment	or Ins. R-30			Componen	ts F1			Inspecte
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation - Fiberglass Faced Batt - R-30	SqFt	1479					
² Labor	Floor Insulation - Fiberglass Faced Batt - R-30	SqFt	1479					
Other Detail								
				_		1 .	Sub Total:	
Field Notes:			Measure	e Sub Total:			L	
Measure 10 CO	Monitor is Needed			e Sub Total:			L	Inspecte
Measure 10 CO Comment		Units		Componen				Inspecte
Measure 10 CO Comment # Material / Labor	Description / Comment			Componen Estimated	<u> </u>	Qty	Actual	
Measure 10 CO Comment # Material / Labor 1 Health and Safety	Description / Comment	Units	Qty	Componen Estimated	<u> </u>		Actual	
	Description / Comment y CO monitor	<i>Units</i> Each	Qty 1	Componen Estimated	<u> </u>		Actual	
Measure 10 CO Comment # Material / Labor 1 Health and Safety 2 Labor	Description / Comment y CO monitor	<i>Units</i> Each	Qty 1	Componen Estimated	<u> </u>		Actual	Inspecte
Measure 10 CO Comment # Material / Labor 1 Health and Safety 2 Labor	Description / Comment y CO monitor	<i>Units</i> Each	Qty 1	Componen Estimated	<u> </u>		Actual	
Measure 10 CO Comment # Material / Labor 1 Health and Safety 2 Labor	Description / Comment y CO monitor	Units Each Hour	Qty 1 1	Componen Estimated	<u> </u>	Qty	Actual	

1	Measure 11 Fix I	mproper Venting (Cloth	nes Dryer		Componen	ts			Inspected
C	omment								
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Equipment	Each	1					
2	Labor	Labor	Hour	1					
C	Other Detail								
				Measur	e Sub Total:		;	Sub Total:	
	Measure 12 Insta omment	ıll aerator showerhead			Componen Estimated			Actual	Inspected
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Unspecified	Misc Material	Each	1					
C	Other Detail								
L									
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

	Measure 13 Insta	II Bathroom Exhaust F	an		Componen	ts			Inspected
C	omment								
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Bathroom exhaust fan	Each	1					
2	Labor	Labor	Hour	1					
(Other Detail								
L									
L] []		
				Measur	e Sub Total:		,	Sub Total:	
	Measure 14 Insta	ıll Kitchen Exhaust Far	1		Componen				Inspected
C	omment				Estimated			Actual	
<i>C</i>	omment Material / Labor	Description / Comment	Units	Qty	•		Qty		Inspected Total
<i>C</i>	omment Material / Labor				Estimated		Qty	Actual	
C #	omment Material / Labor	Description / Comment	Units	Qty	Estimated		Qty	Actual	
C # 1	Comment Material / Labor Health and Safety	Description / Comment Kitchen exhaust fan	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
C # 1	Material / Labor Health and Safety Labor	Description / Comment Kitchen exhaust fan	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
C # 1	Material / Labor Health and Safety Labor	Description / Comment Kitchen exhaust fan	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
C # 1	Material / Labor Health and Safety Labor	Description / Comment Kitchen exhaust fan	Units Each Hour	Qty 1 1	Estimated			Actual	
C # 1	Material / Labor Health and Safety Labor	Description / Comment Kitchen exhaust fan	Units Each Hour	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	
C # 1	Material / Labor Health and Safety Labor Other Detail	Description / Comment Kitchen exhaust fan	Units Each Hour	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	

		all plumbing, electrica e penetrations with cau		n	Componen	ts			Inspected
C	Comment								
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1					
(Other Detail							·	
ĺ	Jener Detain								
Ī									
				Measur	e Sub Total:]	Sub Total:	
	Measure 16 Smo	ke Detector is Needed			Componen				Inspected
C	Comment				Estimated	1		Actual	
<i>C</i>	Comment Material / Labor	Description / Comment	Units	Qty	-		Qty		Inspected Total
<i>C</i>	Comment	Description / Comment	<i>Units</i> Each	Qty 1	Estimated	1	Qty	Actual	
# 1	Comment Material / Labor	Description / Comment			Estimated	1	Qty	Actual	
6 # 1 2	Comment Material / Labor Health and Safety	Description / Comment Smoke detector	Each	1	Estimated	1	Qty	Actual	
t 1 2	Comment Material / Labor Health and Safety Labor	Description / Comment Smoke detector	Each	1	Estimated	1	Qty	Actual	
t 1 2	Comment Material / Labor Health and Safety Labor	Description / Comment Smoke detector	Each	1	Estimated	1	Qty	Actual	
6 # 1 2	Comment Material / Labor Health and Safety Labor	Description / Comment Smoke detector	Each	1 1	Estimated	1		Actual	

Measure 17 Vapor Barrier Needed (Basement/Crawlspace)					Inspected				
C	omment								
				Estimated	1		Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Basement / crawlspace vapor barrier	Each	1					
2	Labor	Labor	Hour	1					
(Other Detail				1				
				Measur	e Sub Total:] ;	Sub Total:	
	Field Notes:								
			Work Or	der Gra	nnd Total:		Gran	d Total:	